ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W0982, W1393, W1715, W0980, W0984, W1395, W1727, W	NA, 4th Crs, 5th Main Rd, 4th Main Rd	Jakkur Village Right side
Segment No.	**Total Length (m)**	
5/C-W0982/S113319	269.29	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	66.26	77.606684	13.078430	77.607269	13.078260	W1727	W1729
2	99.97	77.606216	13.077580	77.607123	13.077430	W0798	W0990
3	103.06	77.606114	13.077325	77.607044	13.077167	RI-S49	W1395

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Jakkur Village Right side in ward no 5 Byatarayanapura Sub-Division Yelahanka zone	4000000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Roads and Drains at Jakkur Village Right side in ward no 5 Byatarayanapura Sub-Division Yelahanka zone	005-16-000003
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/204/2015-16	05/02/2016	120 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
05/02/2016	04/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
GOPI REDDY		0.00
Phone No.	**E-Mail ID**	

AE/AEE

7760405418

Field Inspection Details

Number of Trees	Any Other Information	Name
5		chandrakanth
Date of Inspection	**Remarks**	
07/06/2016		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0982, W1393, W1715, W0980, W0984, W

Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAI	07/06/2016	07/07/2016	COMPLETED
SE	VASU K M	07/06/2016	07/07/2016	COMPLETED
EE	YARAPPA REDDY	07/06/2016	07/07/2016	COMPLETED
AEE	J N LOKESH	07/06/2016	07/07/2016	COMPLETED
AE	CHANDRAKANTH	07/06/2016	07/07/2016	COMPLETED
AE	CHANDRAKANTH	07/06/2016	07/07/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0982, W1393, W1715, W0980,